

Photo Report



Photo position correlates with photo number below.



Photo 1: Main entrance road to the farm, area left and right of road was previously cultivated.



Photo 2: Secondary road flanked by large pine trees.



Photo 3: Existing bulk water supply point to the farm, from where the existing two dams are filled.



Photo 4: Established vineyards on the farm.



Photo 5: Lawfully disturbed areas to be expanded for vineyards, note dense alien stands due to years of seedbed. Alien Clearing is ongoing on site.



Photo 6: Dam 1 showing landscaped vegetation.



Photo 7: Showing Dam 1 from above.



Photo 8: Area below Dam 1 within which the new dam (bottom left corner) is proposed. Fence NOT indicative of property boundary which is well beyond the fence. This area is largely proposed for cultivation and has undergone extensive alien clearing or will require extensive alien clearing (beyond the security fence).



Photo 9: Dam 2 proposed for expansion, surrounded by alien vegetation and bare exposed soil areas.



Photo 10: Intact quality fynbos will not be cultivated.



Photo 11: Degraded areas previously disturbed proposed for cultivation.



Photo 12: Dam 3, to remain as is.



Photo 13: property boundary indicated by the fence and showing the neighbouring land uses to the north.