

Points where photos were taken of the site





*Photo A: View from the gravel road along the south-west boundary of the property showing the remaining natural vegetation and the gentle sloping of the area looking down towards the Theewaterskloof Dam.*



*Photo B: View from the gravel road on the south-western boundary showing the point where the off-site drainage line flows underneath the road and into the property (culvert). One can see in the background the indigenous vegetation that is lightly invaded by alien species. Note the powerline servitude running overhead.*



*Photo C: Drainage sump, down slope of the culvert within the property boundary on the edge of the demarcated wetland. Image was taken looking south/upslope.*



*Photo D: View from the edge of the cleared area on the western property boundary, looking northeast showing the portion of the platform already constructed. The central trench runs along the right of the photo.*



*Photo E: View from the eastern edge of the cleared area. The central drainage trench is visible with IdeaFruit pack shed and its crate storage prominent in the background with the cleared area and concrete platform visible in the foreground.*



*Photo F: View from the north-east edge of the cleared area. On the left one can see the indigenous vegetation. The gentle slope of the property is evident from this image.*



*Photo G: View the north-west corner of the cleared area looking north. In the foreground is the historical trench, with a new culvert and crossing, and, in the background (left), the IdeaFruit pack shed.*