

Figure 1: Photopoints on site



Figure 2: Photopoints along Malgas Infanta Road Nr 268



Figure 3: Photopoints around Gravel Quarry



Figure 4: Photopoints around Dams



Figure 5: Photopoints around Quarry (proposed lodge site)




Figure 6: Photopoints around Landowner's house

Photoreport site visit 11 June 2022:




Photo 1: Farm entrance Harvest Moon – looking along road towards Malgas/ Swellendam



Photo 2: Farm entrance Harvest Moon – looking along road towards Infanta



Photo 3: Proposed lodge site at quarry – looking upstream Breede River towards Malgas/ Swellendam



Photo 4: Proposed lodge site at quarry – looking downstream Breede River towards Infanta and Witsand



Photo 5: Proposed lodge site at quarry – looking northwest over site



Photo 6: Proposed lodge site at quarry – looking north over site



Photo 7: Proposed lodge site at quarry – looking southwest over site



Photo 8: Servitude road adjacent to proposed lodge site – looking south along fenceline



Photo 9: Servitude road adjacent to proposed lodge site – looking north along fenceline



Photo 10: East Servitude road entrance (looking East towards Infanta)



Photo 11: East Servitude road entrance (looking onto farm)



Photo 12: East Servitude road entrance (looking West towards Malgas/ Swellendam)



Photo 13: Gravel Quarry entrance (looking West towards Malgas/ Swellendam) – will become new main entrance to site



Photo 14: Gravel Quarry entrance (looking East towards Infanta) – will become new main entrance



Photo 15: Gravel Quarry – looking East over site



Photo 16: Gravel Quarry – looking West over site



Photo 17: Gravel Quarry – looking South over site



Photo 18: Gravel Quarry – looking North over site




Photo 19: Existing road to proposed lodge site (looking East)



Photo 20: Road to Dams (looking northwest)



Photo 21: Eye area feeding dams (looking North)



Photo 22: Eye area feeding dams (looking North)



Photo 23: Small dam wall – looking West over damwall



Photo 24: Small dam – looking South over dam



Photo 25: Small dam – note outflow culvert (indicated by yellow arrow)



Photo 26: Small dam – outflow culvert downstream



Photo 27: Larger downstream dam – looking North over dam




Photo 28: Larger dam – note two culverts' inflow (indicated by yellow arrows)



Photo 29: Larger dam – two culverts' outflows downstream



Photo 30: Larger dam – pump station and solar panels. Note swale taking stormwater downstream from pumpstation area (indicated by yellow dotted arrow to indicate flow)



Photo 31: Larger dam – swale taking stormwater downstream from pumpstation area (yellow dashed arrow to indicate flow)



Photo 32: New landowner's house (looking East)



Photo 33: New landowner's house (looking northeast)

Site visit 12 August 2025 (additional to photopoint 32 and 33):



Photo 34: Two cottages and parking/utility building



Photo 35: Two cottages and parking/utility building



Photo 36: Most eastern cottage is closest to watercourse on the right.



Photo 37: Watercourse, small dry catchment