

Site visit 18 October 2025:



Figure 1: Photopoints



Photo 1: Southeast corner of site looking North – note walkway seaward side of perimeter fence



Photo 2: Southeast corner of site looking South – houses on Hoekstreet



Photo 3: Drainage line taken on Infanta Road (facing East)



Photo 4: Drainage line taken on Infanta Road (facing West)



Photo 5: Existing platform on site (seaward side of house)



Photo 6: Existing braai and washing line area



Photo 7: View from existing access gate along existing access roads (looking East)



Photo 8: Existing Garage and House (red arrow points to existing storeroom)



Photo 9: Existing beach access gate



Photo 10: Existing derelict concrete slab (looking South)



Photo 11: General waste collection area for Infanta (on Infanta to Malgas Road)