

## PHOTO REPORT




Figure 1: Photo Positions



Photo 1: R 102 view towards the south, site on right pointed by arrow.



**Photo 2:** Taken from R 102, view towards the west, site is fenced with razor wire to attempt to stop illegal dumping.



**Photo 3:** Taken from R 102 view towards the west, most southern corner of site, fence stolen by neighboring squatters.



**Photo 4:** Taken from R 102, view towards the east, Shoprite Eastern Cape Distribution Centre (DC) and the squatter settlement in view.



**Photo 5:** Municipal owned property on the right of the DC fence where the Municipal stormwater culvert will be located as per arrow.



**Photo 6:** Taken from Tynira Road view towards the north, site in distance, extensive litter visible.



**Photo 7:** Northwestern border of the site, razor wire fence was stolen.



**Photo 8: View towards the east, prior to the applicant ownership the site was used as an illegal dumpsite.**



**Photo 9: None notwithstanding dumping, most vegetation on site is hacked, left to dry and then collected for firewood.**



**Photo 10:** View towards the north-west, evidence of old building material dumped on site, various informal footpaths and large heaps of cut to dry vegetation dominating the landscape.



**Photo 11:** Illegal asbestos dumping, subjected to the required safe removal procedures when development takes place.



**Photo 12: Most southern edge of current bush clearing for firewood purposes.**



**Photo 13: Area least affected by illegal dumping and bush clearing.**



**Photo 14: Previous excavation works on site.**



**Photo 15: Cleared open and trampled areas**



**Photo 16: Dumped asphalt.**



**Photo 17: Criminal activity is rife in the area, armed security required for any site visits**