



APPENDIX D – PHOTO REPORT

Prepared by: PHS Consulting

Points where photo's were taken onsite

Legend

- Photo
- Portion 54 of Farm 516

Photo 2

Photo 3

Photo 4

Google Earth

Image © 2025 Airbus



100 m

Points where photo's were taken onsite

Legend

- Photo
- Portion 54 of Farm 516



Photo report for site visit conducted on 12 August 2025:



Photo 1: View of the turnoff from the Malgas-Infanta Road onto the access road that leads to the farm.



Photo 2: View along internal farm access road, facing southwest (towards the Malgas-Infanta road). The caretakers cottage can be seen in the middle of the photo to the right of the road.



Photo 3: View of the cleared area around the new caretakers cottage located in the southern portion of the property, adjacent to the farms internal access road (facing south)



Photo 4: View of the cleared area around the new caretakers cottage located in the southern portion of the property, adjacent to the farms internal access road (facing north)



Photo 5: Overview of the cleared area around the main dwelling, viewed from the existing jetty



Photo 6: View of a portion of the cleared area around the main dwelling (facing east)



Photo 7: View of a portion of the cleared area around the main dwelling (facing southeast)



Photo 8: View of a portion of the cleared area around the main dwelling where a new pumproom has been constructed and additional water tanks have been installed.



Photo 9: View of a portion of existing cleared area around the main dwelling



Photo 10: View of a portion of existing cleared area behind the main dwelling.



Photo 11: Existing jetty leading to the Breede River



Photo 12: View of a portion of the cleared area within the floodplain saltmarsh (facing north)



Photo 13: View of a portion of the cleared area within the floodplain saltmarsh (facing south)



Photo 14: View of a portion of the cleared area within the floodplain saltmarsh (facing south)