



*Photo 1: Wetland area proposed for rehabilitation. This photo was taken facing northwest. This wetland is impacted by canalisation, compaction, rubbish dumping the spread of alien invasive vegetation and polluted water inflow. The EFRC Poultry Abattoir can be seen in the middle left of the photo.*



*Photo 2: Wetland area proposed for rehabilitation. This photo was taken facing east. This wetland is impacted by canalisation, compaction, rubbish dumping, the spread of alien invasive vegetation and polluted water inflow. A residential area can be seen in the background.*



*Photo 3: Wetland area proposed for rehabilitation. This photo was taken facing east. This wetland is impacted by canalisation, compaction, rubbish dumping, the spread of alien invasive vegetation and polluted water inflow. A residential area can be seen in the background.*



*Photo 4: Wetland area proposed for rehabilitation. This photo was taken facing northeast. Despite the disturbances, present within the wetland area, patches of indigenous vegetation such as *Juncus* spp., *Typha* spp., *Paspalum distichum*, and *Psoralea* spp. are present, with some plants still in a healthy state.*