Historical Photographs of Erf 134 and Timeline on Infrastructure:



Figure 1: 1981 Photograph showing house (red circle) and access road (red arrow) in place on Erf 134 (CDNGI Geospatial Portal).



Figure 2: 1989 Photograph showing additional cleared area for shed (red arrow) on Erf 134 (CDNGI Geospatial Portal). Cleared area around house and access road to house also evident.




Figure 3: 1999 Photograph showing previously cleared areas for existing infrastructure remain in place on Erf 134 (CDNGI Geospatial Portal).



Figure 4: 2005 Photograph showing previously cleared areas for existing infrastructure remain in place on Erf 134 (CDNGI Geospatial Portal).