
Points where photos were taken of the site
F
G
E
D
C
B
A
Google Earth
Image © 2025 Airbus
N
200 m



Photo A: View from the south-west boundary of the property showing the remaining natural vegetation and the gentle sloping of the area.



Photo B: View from the road on the western boundary showing the point where the drainage line goes underneath the road and into the property (culvert). One can see in the background the indigenous vegetation that is lightly invaded by alien species.



Photo C: Drainage sump, down slope of the culvert within the property boundary on the edge of the demarcated wetland. Image was taken looking south/upslope.



Photo D: View from the edge of the cleared area on the western property boundary, looking north east.



Photo E: View from the eastern edge of the cleared area. From left to right one can see the drainage trench, IdeaFruit, and the concrete platform.



Photo F: View from the north-east edge of the cleared area. On the left one can see the indigenous vegetation. The gentle slope of the property is evident from this image.



Photo G: View the north-west corner of the cleared area looking north. At the foreground is the large trench and, in the background, IdeaFruit.